



	SMA	
<b>RLS-1-1064-SMA*</b>		
		1062~1066
		2
		400
		SMA
		3
	/	0,28
		0,4
		3,3
		1,45
	( ), °C	+18~+30
	, °C	-10~+55
	, °C	-20~+60
	**	Pt1000 / NTC10k
	(LxWxH),	50x30x18
	(LxWxH),	61,8x46,2x18
		250
		1

\*

\*\*

[www.lascompany.ru](http://www.lascompany.ru)

[info@lascompany.ru](mailto:info@lascompany.ru)

/ : +7(812)448-08-13

